

Recap: Ed's suggestion how to read Decoded output



No Rocs, Token bypassed.

Header

0111 1111 1100 Header ID

0000 0001 Event Number

0000 0001 Status bits

Trailer

0111 1111 1111 Trailer ID

0110 0010 Status Bits (TBM Reset, ROC Reset, Cal Trigger)

0100 0000 Temperature/Status Bits (Ignore this)



Recap: Ed's suggestion how to read Decoded output



No Rocs, Token not bypassed.

Header

0111 1111 1100 Header ID

0000 0001 Event Number

0000 0001 Status bits

Trailer

0111 1111 1111 Trailer ID

0110 0010 Status Bits (TBM Reset,ROC Reset,Cal Trigger)

0100 0000 Temperature/Status Bits (Ignore this)



HDI #19 (The Good One)



```
decode
1000 words allocated for data buffer
size = 4
size = 4
                                Header
#samples: 4 remaining:
                                Trailer
 FF7F=1111111101111111
                                Status bits (TBM reset etc)
 C010=1100000000010000
 17FF=0001011111111111
                                (looks like
 6240=0110001001000000
                                token is bypassed
                                as we don't see
                                garbage between
#samples: 4 remaining:
                                Status bit and trailor:
 FF7F=1111111101111111
 C010=1100000000010000
                                but Mike/Ashish
                                confirmed that
 17FF=00010111111111111
                                token is not bypassed
 6240=0110001001000000
                                for these HDI's)
```



How startmod3 was modified?



```
-- setup TBM
modsel b11111
modsel 0
                  Init TBM, Reset ROC
tbmset $E4 $F0
tbmset $F4 $F0
tbmset $E0 $00
                  Disable PKAM Counter
tbmset $F0 $00
                  Mode = Calibration
tbmset $E2 $C0
tbmset $F2 $C0
tbmset $E8 $02
                  Set PKAM Counter
tbmset $F8 $02
tbmset $EA b00000000 Delays (?)
tbmset $FA b00000000
tbmset $EC $00 Temp measurement control
tbmset $FC $00
mdelay 100
```

(Robert suggested disabling the trigger to the ROCs)

tbmset \$E0 \$40 tbmset \$F0 \$40



Recap: How Status Bit looks like



No Rocs, Token not bypassed, No Trigger Output Bit Set.

Header

0111 1111 1100 Header ID

0000 0001 Event Number

0000 0001 Status bits

Trailer

0111 1111 1111 Trailer ID

1110 0010 Status Bits (No Token Pass, TBM Reset, ROC Reset, Cal Trigger)

0100 0000 Temperature/Status Bits (Ignore this)





This HDI had problem with Core A

(after disabling the trigger to the ROCs)

```
size = 4
size = 4
#samples: 4 remaining: 0
 EFF8=11101111111111000
 0202=0000001000000010
 OFEC=0000111111101100
 481F=0100100000011111
#samples: 4 remaining: 0
EFF8=11101111111111000
 0202=0000001000000010
FFEC=11111111111101100
481F=0100100000011111
```

```
size = 4
size = 4
#samples: 4 remaining: 0
 7FC0=0111111111000000
1817=0001100000010111
FFE2=1111111111100010
COFF=11000000111111111
#samples: 4 remaining: 0
 7FC0=0111111111000000
 1817=0001100000010111
FFE2=1111111111100010
COFF=11000000111111111
```

Note: Perfect Trailer – followed by Status Bit for No Trigger Output







```
size = 4
#samples: 4 remaining: 0
 7FC0=0111111111000000
 1817=0001100000010111
 FFE2=1111111111100010
 C0FF=11000000111111111
#samples: 4 remaining: 0
 7FC0=0111111111000000
 1817=0001100000010111
 FFE2=1111111111100010
 C0FF=11000000111111111
```

(after disabling the trigger to the ROCs)

And .. Same observation for HDI #18, #20

Inference: Decoder working fine – disabling the trigger out the problem goes away. (Mike Matulik/Ashish confirmed that the token bypass is not wire bonded.)



Back up: HDI pads



